Intertek Caleb Brett

ITS Testing Services (M) Sdn Bhd. (7379-A)
C/o Fima Bulking Services Sdn. Bhd., Jalan Parang, 2nd extension, North Port, 42000 Port Klang, Selangor, Malaysia.
Tel.: 603-31766179/31765400 Fax. 03-31767178 Tlx. CBPK MA 39896 E-mail. itslab@intertek.com

Our Ref : ITSPK/LB/4865/2006
Date : 7th August 2006

CERTIFICATE OF ANALYSIS

Representing : INSULFLEX SDN. BHD.
Kawasan Perusahaan Bangi
43650 Bandar Baru Bangi
Selangor.

The following is a report on the analysis of one (1) sample stated to be INSULFLEX CLOSECELL INSULATION (RUBBER FOAM) received on 2nd August 2006.

Results of Analysis

Test	Methods	Reporting Limit	Results
Cadmium (Cd)	With reference to USEPA 3052, by microwave digestion and determined by ICP-OES	2 ppm	Not Detected
Chromium VI (Cr^{6+})	With reference to USEPA 3060A & 7196A, by alkaline digestion and determined by UV-Vis	1 ppm	Not Detected
Lead (Pb)	With reference to USEPA 3052, by microwave digestion and determined by ICP-OES	2 ppm	Not Detected
Mercury(Hg)	With reference to USEPA 3052, by microwave digestion and determined by ICP-OES	2 ppm	Not Detected
Polybrominated biphenyls (PBBs) / Polybrominated diphenyl ethers (PBDEs)	With reference to USEPA 3540C, by solvent extraction and determined by GC-MSD	10 ppm	Not Detected

Remarks : Test portion was "Totally Dissolved" for the testing of Cadmium, Lead & Mercury in pre-conditioning sample treatment.

Test Performed by : Rosnani Umar

ITS TESTING SERVICES (M) SDN BHD

KHOR AI TIN
M.Sc., AMIC

This report shall not be reproduced except in full, without the written approval of the laboratory.

TERMS AND CONDITIONS OF BUSINESS
"All work performed by **ITS Testing Services (M) Sdn. Bhd.** is in accordance with the relevant **International Federation of Inspection Agencies (IFIA) Guidelines** and in accordance with **ITS Testing Services (M) Sdn. Bhd.**'s Standard Terms and Conditions or Business, a copy of which will be provided upon request."